

MATERIAL SAFETY DATA SHEET

NPCA 1-72

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

DATE OF PREP. 4-15-85

Section I

MANUFACTURER'S NAME REXNORD CHEMICAL PRODUCTS INC.
Sonneborn Building Products

STREET ADDRESS 7711 Computer Ave. CITY, STATE, AND ZIP CODE Minneapolis, MN 55435

EMERGENCY TELEPHONE NO. 612/835-3434

PRODUCT CLASS MANUFACTURERS CODE IDENTIFICATION

TRADE NAME KURE-N-SEAL Product #495 (BP3224)

Section II - HAZARDOUS INGREDIENTS

INGREDIENT	PERCENT	TLV		LEL	VAPOR PRESSURE
		PPM	mg/m ³		
Solvent, Naphtha (Petroleum) Light Aromatic (CAS #64742-95-6)	67	100		1.0	< 1 mm Hg @ 20°C
Solvent, Naphtha (Petroleum) Medium Aliphatic (CAS #64742-88-7)	18	200		0.7	2.0 mm Hg @ 20°C

Section III - PHYSICAL DATA

BOILING RANGE 150 - 200°C VAPOR DENSITY ☒ HEAVIER, ☐ LIGHTER THAN AIR

EVAPORATION RATE ☐ FASTER ☒ SLOWER THAN ETHER PERCENT VOLATILE BY VOLUME 88 WEIGHT PER GALLON 7.2 lbs.

Section IV - FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY Combustible FLASH POINT 101°F LEL 0.7

EXTINGUISHING MEDIA Foam, carbon dioxide, dry chemicals.

UNUSUAL FIRE AND EXPLOSION HAZARDS Closed container may explode when heated.

SPECIAL FIRE FIGHTING PROCEDURES

Contains solvents. Do not use water to extinguish fire.

Section V — HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE 100 PPM

EFFECTS OF OVEREXPOSURE

Inhalation: lightheadedness, dizziness, unconsciousness.

EMERGENCY AND FIRST AID PROCEDURES

INHALATION: Remove patient to fresh air.

SKIN CONTACT: Wash thoroughly with soap and water.

EYE CONTACT: Flush with clean water for a minimum of 15 minutes.

INGESTION: DO NOT induce vomiting. CALL A PHYSICIAN-IMMEDIATELY!

Section VI — REACTIVITY DATA

STABILITY ☐ UNSTABLE ☒ STABLE

CONDITIONS TO AVOID

INCOMPATIBILITY (Materials to avoid)

HAZARDOUS DECOMPOSITION PRODUCTS

HAZARDOUS POLYMERIZATION ☐ MAY OCCUR ☒ WILL NOT OCCUR

CONDITIONS TO AVOID

Section VII — SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Avoid prolonged breathing of vapors. Remove sources of ignition. Blot up with paper or rags.

WASTE DISPOSAL METHOD

In accordance with state, federal and local regulations.

Section VIII — SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION

None required if ventilation is adequate. If used in confined areas with no ventilation, use Mine Safety Appliances - mask & cannister:

Organic Vapor Mask (No. 457081)

Organic Vapor Cannister (No. 77705GMA) or 3M Brand #8712 Organic Vapor Respirator or NIOSH/MSHA approved equivalent

VENTILATION

Positive air ventilation. Use portable fans if working in small enclosed areas.

PROTECTIVE GLOVES

Rubber gloves

EYE PROTECTION

Goggles or face shield

OTHER PROTECTIVE EQUIPMENT

-

Section IX — SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Keep away from heat, sparks, and open flame. Keep container tightly closed when not in use.

OTHER PRECAUTIONS

KEEP OUT OF THE REACH OF CHILDREN.